APR Assessors Ltd
6 Burnham Road
Albany Park
Sidcup
Kent
DA144PY

Engineers Report - Total Loss

12-November-2010
Our Ref : SAMPLE REPORT
Your Ref / Claim No. : SAMPLE REPORT

Dear Sirs,

In accordance with your recent instruction we confirm that we have completed our inspection on 18-October-2010. Our report for the inspection, made at; APR Assessors Ltd, 6 Burnham Road Albany Park, Sidcup, Kent, DA144PY is detailed below.

Insurance and Assessment Details

Policy Cover : TBA
Loss Date : 10-October-2010
VAT Status : Unknown
Excess Applicable : Unknown

APR Reference : SAMPLE REPORT
Authorisation : Not Authorised
Date Authorised :

Insured

Name : APR Assessors Ltd
Mobile No : 07703533456
Phone No : 02083069306
Fax No : 02083026449
eMail : info@apr-assessors.co.uk
VAT Reg No. 981 4645 91

Address : 6 Burnham Road Albany Park, Sidcup, Kent DA144PY

Damage and Impact

The vehicle has sustained collision damage. Please see the impact picture below for the exact primary and secondary impact points and for the direction of the impact. The severity of the damage is medium. Prior Damage. The vehicle was noted to be in a good condition. The vehicle has previous, old and unrelated damage to: the offside edge of the front bumper is scuffed and the offside and nearside corners of the rear bumper are scuffed.
The vehicle does have average kilometres for the make, model and year, and along with the general condition has been valued accordingly. We have utilised such internet sources as "Exchange and Mart & Auto Trader" to assist in the valuation process of the vehicles pre collision value, this information has been kept on file and is available on request. In our opinion the vehicle was not roadworthy at the time of our inspection as a result of the damage sustained.

Vehicle

Registration No : R395TAC
VIN : CXR10-0135950
Vehicle Type : Car
Vehicle : TOYOTA AERAS MPV 4 DOOR 2.2 DIESE
Production Year : 1998
Registration Date :
Colour : Red & Silver
Finish Type : Metallic Clear Overbase
Odometer : 112,928 Km
Transmission : Automatic
Head Restraints : Fitted

Underside:

Impact Key
Horizontal Points
Primary
Secondary
Above / Below Points
Primary
Secondary

Steering Serviceable : *No !*
Brakes Serviceable : Yes
Airbag / Pretensioner Deployed : No

Tyre Treads

Front Left :	4.0 mm	**Front Right :**	5.0 mm	**Rear Left :**	3.0 mm	**Rear Right :**	5.0 mm

Repair Method

New Parts	Front Bumper; Front Bumper Bracket, L; Front Bumper Support, L; Front Bumper Spoiler, L; Headlamp Assy, L; Flasher Lamp Assy, L; Front Wing, L; Front Wing Splashguard, L; Front Wing Moulding, L; Front Susp Hub, L; Front Susp Knuckle, L; Front Susp Strut, L; Front Susp Spring, L; Front Susp Insulator, L Lwr; Front Door Moulding, L Lwr; Front Door Finisher, L; Membrane; Bolts; Clips; Sundry Items.
Repair	Bonnet; Front Door Shell, L.
Overhaul	O/H Front Suspension, L.
Remove and Install	Ri Front Bumper Assy; Ri Headlamp Assy, L; Ri Grille; Met Bonnet; Met Front Wing, L; Met Front Door Shell, L.
Paint	Refin Bonnet; Refin Front Wing, L; Refin Front Door Shell, L.
Check and Adjust	Geometry; Check And Adj Front Wheel Alignment.
Additional Labour	Corr Prot Front Wing, L.
Additional Operations	Re-Furbish: Alloy Wheel, Nearside Front.; Final Check And Road Test; Polish/De-Nibbing.

Key: Corr Prot = Corrosion Protection, L = Left, Met = Mechanical, Electrical and Trim Items, R = Right, Refin = Refinish, Ri = Remove and Install.

Repair Cost

Parts	1,266.33
Labour (23.1 hrs @ 36.00 per hour)	831.60
Paint Materials	203.94
Workshop Materials	0.00
Miscellaneous Charges	125.00
Subtotal (excludes VAT)	2,426.87
VAT (@ 17.50%)	424.70
TOTAL REPAIR COST (inc VAT)	**2,851.57**

Storage and Recovery Charges

Storage :	
Start Date :	
Price per day (excludes VAT) **:**	0.00
Recovery :	0.00
Inherited Recovery :	0.00
TOTAL RECOVERY CHARGES :	**0.00**

Vehicle Valuation

	Retail	Trade	Private Sale	Disposal	Miles (000)
Glass's Guide	0.00	0.00	0.00	0.00	
Mileage Adj +/-	0.00	0.00	0.00	0.00	
Options Adj +/-	0.00	0.00	0.00	0.00	
Condition Adj +/-	0.00	0.00	0.00	0.00	
Glass's Guide Total	0.00	0.00	0.00	0.00	

Pre-Acc Condition :	Good
GlassCode :	N/A
Guide Edition :	
Salvage Value :	161.00
Insured Value :	0.00

Engineers Value Retail : 0.00 **Engineers Value Trade :** 0.00

ENGINEERS PRE-ACCIDENT VALUE : 2,150.00

Salvage

We recommend that this vehicle is treated as Category C salvage. It is therefore suitable to be sold as repairable salvage. The salvage reference is; @7.5% N/RWORTHY.
We recommend the following salvage agent; T.B.A. Cat C

Remarks

Instruction Date: 15/10/2010
Inspection Date: 18/10/2010
Assessment Date: 18/10/2010
Report Date: 19/10/2010

Note:
There has been a slight delay in the inspection and report as the claimant who wished to be present at the time of the inspection was not available on the date of instruction and the date of our original inspection attempt so we made arrangements to inspect the vehicle the next available working day that the claimant was available.

The vehicle has the following extras:
Air Bag Passenger & Driver
Air Conditioning
Alloy Wheels
CD Radio Cassette
Privacy Glass
Rear Spoiler
Roof Bars

Reversing Mirror
Twin Sun Roof

The vehicle was found to be mobile, not roadworthy an not in use at the time of the inspection.

The vehicle has been considered as not being roadworthy as there is collision damage to the nearside front of the vehicle including damage to the near side front wing, the nearside front lamp combination unit, the nearside front door and the nearside front alloy wheel, tyre and suspension. The nearside front tyre now rubs on the upper of the nearside front spring and on full left hand lock also rubs on the nearside front chassis leg. The near side front door front leading edge rubs on the nearside rear edge of the nearside front wing and does not allow the nearside front door to open fully.

The vehicle is a P.C.O. registered vehicle and is currently not fit for this purpose.

To reinstate this vehicle to its pre-accident condition is considered to be uneconomical, therefore we recommend that the vehicle is dealt with on a total loss basis. We have calculated the pre-accident value to be £2150.00 with a salvage value of £161.00. The value is subject to consideration of the vehicle registration document, MOT and service records.
We are not aware of any outstanding recovery or storage charges.
Our instructions on your behalf were entirely without prejudice.
We have not made contact with the owner and have not given instructions in the matter.
We understand that the vehicle is not currently being used by the owner.
In our opinion, temporary repairs would not be possible or economically viable to make the vehicle roadworthy.
We confirm that we do have photographs of this vehicle available and have attached a copy of them to this report.
This report is based upon the instructions received and on what was visible to us at the time of our inspection.
We declare that we understand our duty in providing this report to the court and we confirm that we have complied with that duty. We understand that this duty overrides any other obligation.
We trust that the foregoing will be of assistance to you and we take this opportunity to enclose a note of our fee for your kind consideration.
I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

60
40
80
100
120
80
60
km
20
40
140
20
160
100
180
km/h
km
MPH

TOYOTA MOTOR CORPORATION
MODEL KD-CXR10G-RRSVT
ENGINE 3C-TE 2184 cc
FRAME No. CXR10-0135950
COLOR TRIM GVM(KG)
3J7 YE12
TRANS./AXLE A45DE F282
PLANT/BUILT C25
30881
トヨタ自動車株式会社

04 7092173 5
30 04 11
R395 TAC
M
£ 205.00
TOYOTA LUCIDA
PLG
DVLA/EVL
13/04/10
12

burchell assessors
motor claims assessors
consultant motor engineers

burchell assessors
po box 6019 dudley
west midlands dy1 9qg
t: 01384 231313 f: 01384 686111
e: info@burchellassessors.co.uk
w: www.burchellassessors.co.uk

Invoice

To: **Fortis Insurance**
Fortis House
Tollgate
Eastleigh
Hampshire
SO53 3YA

Details

Our Reference :	**IF-EST0038**
Date of Issue :	**21-October-2009**

Insurance Details

Claim Number :	**CLA123456789**
Loss Date :	**01-October-2009**
Insured :	**Mr Bob Frearson**
Make and Model :	**TOYOTA CELICA VVT-I**
Registration No :	**RF06ETA**
Inspection Date :	**02-October-2009**

Inspection Fee

Inspection Report Fee * :	**102.99**

**** Includes VAT @ 21.50%***

© Copyright 2007 Glass's Information Services Ltd. All Rights Reserved.

burchell assessors
consultant motor engineers

burchell assessors
po box 6019 dudley
west midlands dy1 9gg
t: 01384 231313 f: 01384 656111
e: info@burchellassessors.co.uk
w: www.burchellassessors.co.uk

To: A & M Autos
Prussia Street
Dublin 7
Co Dublin

Date :	21-October-2009	**Claim No. :**	CLA123456789
Our Reference :	EST0038	**Company :**	Fortis Insurance
Engineer :	Administrator	**Insured :**	Mr Bob Frearson
Date Inspected :	02-October-2009	**Third Party :**	

Dear Sir or Madam,

Re: Repairs to TOYOTA CELICA VVT-I - RF06ETA

Following our inspection of the above vehicle, please proceed with the repair in accordance with all the terms below. Please contact the Insured to make any neccesary arrangements.

Parts *	1,046.63	
Labour (18.1 hrs @ 40.00 per hour) *	724.00	
Paint Materials *	153.91	
Workshop Materials *	2.88	
Miscellaneous Charges *	20.00	** VAT excluded*

The Insured is responsible to pay a policy excess of 250.00. Please invoice the Insured for this ammount and send a copy of the invoice to us. The Insured is VAT registered, therefore please invoice them for the VAT and send a copy of the invoice to us.

Important. Due to the advanced construction methods of modern vehicles (i.e. High strength steels, etc.), it is the responsibility of the repairer to have the appropriate knowlege, skills and equipment to carry out approved methods of repair. If you do not have the appropriate knowlege, skills or equipment, do not proceed with the repair and advise us immediately. If any problems arise during the repair, please advise the engineer immediately.

No additional labour, parts, materials or other charges will be accepted without prior agreement in writing.

Line 1
Line 2
Line 3
Line 4
Line 5

Yours faithfully

D Burchell

GLASSMATIX

Parts List

RF06ETA | **TOYOTA CELICA VVT-I** | **21-Oct-2009 8:07**

Estimate and Vehicle Details

Estimator :	Administrator	Production Year :	2006
Estimate Date :	1-Oct-2009	Registration Date :	09-Jun-2006
Estimate ID :	EST0038	Colour :	RED
Supplemented :	No	Finish Type :	Clear Overbase
Make / Model :	TOYOTA CELICA VVT-I	Paint Code :	
Registration No :	RF06ETA	Engine Number :	
VIN :	JTDDR38T000189756	Trim Code :	

No.	Part Description	Part Number	Price	Comments
	OEM New			
1	BONNET	53301-20580	368.41	
2	FRONT CHASSIS LEG, R	57101-2B010	678.22	

NOTE: All part numbers should be checked before confirming a parts order. The exact price and part number for any items identified as "Order from supplier" should be verified from a manufacturers parts supplier.

© Copyright 2007 Glass's Information Services Ltd. All Rights Reserved.

GLASSMATIX

Parts List

RF06ETA | **TOYOTA CELICA VVT-I** | **21-Oct-2009 8:07**

Estimate and Vehicle Details

Estimator :	Administrator	Production Year :	2006
Estimate Date :	1-Oct-2009	Registration Date :	09-Jun-2006
Estimate ID :	EST0038	Colour :	RED
Supplemented :	No	Finish Type :	Clear Overbase
Make / Model :	TOYOTA CELICA VVT-I	Paint Code :	
Registration No :	RF06ETA	Engine Number :	
VIN :	JTDDR38T000189756	Trim Code :	

No.	Part Description	Part Number	Price	Comments
	OEM New			
1	BONNET			
2	FRONT CHASSIS LEG, R			

NOTE: All part numbers should be checked before confirming a parts order. The exact price and part number for any items identified as "Order from supplier" should be verified from a manufacturers parts supplier.

© Copyright 2007 Glass's Information Services Ltd. All Rights Reserved.