



Specialist, Smart and Cosmetic Repairs in Glassmatix

15 December 2011

With many repairers now offering smart repairs as an additional service to traditional repair methods, Glass's have now introduced a facility for adding specialist, smart and cosmetic repair methods, directly and transparently into a GlassMatix estimate.

- Each operation can be added either to an assessment containing traditional repairs, or where required, on a separate assessment.
- The operations covered include... **Paintless Dent Repairs, Interior Trim Repairs and Alloy Wheel Refurbishment.**
- The new operations are located in the **PartBase Reference Sheet** in the **Additional Costs** section as displayed in the example picture below...

PartBase - [Assess1 - BMW 5 Series - (915362) TTS (BM2983)]

File Edit View Insert Tools Window News Update Help

REFERENCE SHEET

Description	Cost	Time
Alloy Wheel Refurbish		
Front Wheel, Right		
Front Wheel, Left		
Rear Wheel, Right		
Rear Wheel, Left		
Collection (NEW)		
Congestion Charge, London	8.00	
Corrosion Protection Materials		
Courtesy Car		
Delivery		
Electrical Repairs (NEW)		
EPA Waste Charge		
Estimate Charge		
Inherited Charge		
Inherited Recovery Charge		
Jig Hire Charge		
Miscellaneous Charge		
Paint Materials (* for option entry)		
Paintless Dent Removal (NEW)		
Bonnet		
Bootlid		
Front Door, Right		
Front Door, Left		
Front Wing, Right		
Front Wing, Left		
Rear Door, Right		
Rear Door, Left		
Roof		

Diagram labels: 1A, 1B, 1C, 3, 2, 0

No	Barcode	Labour t	Operatio	Description	Type	Part Number	Cost	Time	CREG
1	936146	B - Body	AO - Addi	PAINTLESS DENT REPAIR, BONNET			50.00	0.0	0.0

For Help, press F1

Location of Repair Type Operations

- Each operation is displayed in a folder by operation type (for example Paintless Dent Removal).
- The operations are charged by default as **Miscellaneous** cost items.
- Alternatively, if required, any of the operations can be charged as a labour cost.

Full List of New and Revised Operations

- **Alloy Wheel Refurbishment** – Revisions to existing section
- **Interior Trim Repairs** – New section
- **Paintless Dent Removal** – New section
- **Electrical Repairs** – New section
- **R&I Screens and Glass** – New section (Previous section in labour folder still remains).
- **Collection** - New operation
- **Transportation to Dealer** - New operation
- **Dashboard Light Reset** - New operation
- **Resets** - Section moved from labour folder to additional costs folder
- **PAS 125 Charge** - New operation (UK only)
- **Method Research Allowance** - New operation (UK only)